

Biosense Laboratories AS  
HIB-Thormøhlensgt. 55  
N-5008 Bergen  
NORWAY  
Phone: +47 55 54 39 66  
Fax: +47 55 54 37 71

## MATERIAL SAFETY DATA SHEET

Prod. No. : **V01013403**

Name: **Medaka vitellogenin ELISA-kit**

Hazards identified with this product are those associated with the following components. Refer to the material safety data sheets for the listed items.

**Component name:**

Phosphate buffered saline (PBS) with Tween 20  
TMB peroxidase substrate

---

### Multiple component spill or leak procedures

---

**Steps to be taken if material is released or spilled**

Wear respirator, chemical safety goggles, rubber boots and heavy rubber gloves.  
Absorb on inert absorbent and place in close containers for disposal.  
Ventilate area and wash spill site after material pickup is complete.

**Waste disposal method**

Dissolve or mix the material with a combustible solvent and burn in a chemical incinerator equipped with an afterburner and scrubber.  
Observe all federal, state and local environmental regulations.

**Label precautionary statements**

May be harmful by inhalation, ingestion or skin absorption.  
Irritating to eyes, respiratory system and skin.  
In case of accident or if you feel unwell, seek medical advice immediately (show the label where possible).  
In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.  
In case of contact with skin, wash immediately with soap and plenty of water.  
Wear suitable protective clothing, gloves and eye/face protection.  
Do not breathe dust.

---

**Other information**

---

The above information is believed to be correct but does not purport to be all inclusive and shall be used only as a guide. Biosense laboratories AS shall not be held liable for any damage resulting from handling or from contact with the above product.

Copyright 2012 Biosense Laboratories

License granted to make unlimited paper copies for internal use only.

Version 2: SW 01.10.12

Supersedes version of (date): BMN 04.11.04

Reason for alteration: Rewiev of MSDS

Changes in Section: None